

VAG-COM
Windows Based VAG/VAS Emulator
Version: Release 409.1-S
www.Ross-Tech.com

Dealer/Shop Name:
Workshop Code: 000 00000

Diagnostic Trouble Code Report
Saturday, 06 May 2017, 14:49:22

VIN Number: License Plate:
Mileage: Repair Order:

Control Module Part Number: 038 906 012 K
Component and/or Version: 1,9l R4 EDC 0000SG 2811
Software Coding: 00002
Work Shop Code: WSC 00046

2 Faults Found:

17965 - Charge Pressure Control: Positive Deviation
P1557 - 35-00 - -

17664 - Engine Coolant Temp Sensor (G62): Open or Short to Plus
P1256 - 35-10 - - - Intermittent

Readiness: N/A